Fleetguard®

New Product Bulletin

Europe, Russia/CIS & Middle East Parts — April 2022

Part Number	Application	Cross-Ref.	Dimensions	Description	Associated Part Numbers*	Segment
 **AF4453**	**Mercedes-Benz Sprinter III** (907, 910) (2018>) (211 CDI/214 CDI/311 CDI/314 CDI/317 CDI/318 CDI/411 CDI/414 CDI/417 CDI) equipped with OM651.950 & OM651.958 engines	**Mercedes-Benz** (A)9105281500 **Mann + Hummel** C43002 **Hengst** E1463L **Wix** WA9899 **Filtron** AP158/4	H: 46.5 mm L: 420mm W: 225 mm	Panel Air Filter	AF56107 (Cabin Air Filter) AF26375 (Panel Air Filter) FF42137 (In Line Fuel Filter) FF5862 (In Line Fuel Filter) LF4000 (Lube Filter)	
AF4458	**Mercedes-Benz Vito III** (447) (2014>) (109CDI, 110CDI, 111CDI, 114CDI, 116 CDI, 119, 119CDI, 119CDI BlueTec, 124CDI, 160CDI, 180CDI, 200CDI, 220CDI, 250CDI) equipped with Mercedes-Benz OM651.950/OM654.920/OM622.851/M274.920 engines	**Mercedes-Benz** (A)6510900051 **Mann + Hummel** C42002 **Hengst** E1332L **Mahle** LX3031 **Filtron** AP158/3 **UFI** 30.A67.00 **Tecnocar** A2570 **Purflux** A1793 **Wix** WA9826 **Bosch** F026400505	H: 33 mm L: 415 mm W: 222.5 mm	Panel Air Filter	AF56107 (Cabin Air Filter) AF56086 (Cabin Air Filter) FF42137 (In Line Fuel Filter) FF5860 (In Line Fuel Filter) FF5862 (In Line Fuel Filter) LF4000 (Lube Filter) LF17523 (Lube Filter, Cartridge) FS20216 (Fuel Water Separator, Cartridge)	

* Partial list of associated parts included here. For full list, please visit our online catalog.

Replaced and/or obsoleted parts

Part number	Replacement PN
3935659	no replacement
3942821	no replacement
3917480	no replacement
3910315	no replacement
3903914	no replacement
3903916	no replacement
3917128S	no replacement
3917129S	no replacement
3940750S	no replacement
3940756S	no replacement
3944520S	no replacement
3950689S	no replacement
3951367S	no replacement
3955640S	no replacement
3955641S	no replacement
3328464S	no replacement
3328567S	no replacement
3328568S	no replacement
3625120S	no replacement
3911277S	no replacement
3912703S	no replacement
3946996S	no replacement

Part number	Replacement PN
3947508S	no replacement
3947509S	no replacement
3951438S	no replacement
3951133	no replacement
3950690S	no replacement
3321978S	no replacement
3322377S	no replacement
3322517S	no replacement
3322518S	no replacement
3322519S	no replacement
3322520S	no replacement
3322521S	no replacement
3323610S	no replacement
3323613S	no replacement
3325470S	no replacement
3326570S	no replacement
3326798S	no replacement
3329059S	no replacement
3320958S	no replacement
3320962S	no replacement
3320966S	no replacement
3320967S	no replacement

Part number	Replacement PN
3321590S	no replacement
3321592S	no replacement
3321861S	no replacement
3321967S	no replacement
3321968S	no replacement
3321969S	no replacement
3321970S	no replacement
3929113	no replacement
3941470	no replacement
3941964	no replacement
3913035S	no replacement
3913038S	no replacement
3913057S	no replacement
3917100S	no replacement
3917101S	no replacement
3933037S	no replacement
3936434S	no replacement
3939391S	no replacement
3939393S	no replacement
3939392S	no replacement
3939441S	no replacement
3939442S	no replacement

Part number	Replacement PN
3939443S	no replacement
3939461S	no replacement
3946989S	no replacement
3946990S	no replacement
3946991S	no replacement
3968804S	no replacement
3982840S	no replacement
3321577S	no replacement
3321578S	no replacement
3321579S	no replacement
3917215	no replacement
3919181	no replacement
3919182	no replacement
3919184	no replacement
3919185	no replacement
3936328	no replacement
3938954	no replacement
3944694	no replacement
3970397	no replacement
3974949	no replacement
3974950	no replacement